

Gorman-Redlich
257 West Union Street
Athens, Ohio 45701

Fax: (740) 592-3898

PH: (740) 593-3150

email jimg@gorman-redlich.com

www.gorman-redlich.com

AMBER ALERT INFORMATION

The “AMBER” codes have been available since June 1, 2002 in the Version 9.2 firmware of our EAS equipment.

1. If Version 9.2 is installed you have the AMBER codes. It is currently installed in our EAS equipment sold since June, 2002.
2. If you have version higher than V6.4. Return the equipment to us for the update, which involves changing the EPROM. The charge is \$50 plus return shipping.
- 3...If you have a version V6.4 or lower. Return the equipment to us for the update which involves changing the board from a REV C to a REV E for \$150.00 Then installing the new EPROM for additional \$50 This update would total \$200 plus shipping.

To determine the version of firmware you have in your unit. Power down the equipment and then power it up. On the second line of the display for about 2 seconds the version of firmware will be displayed.